



## **APPENDIX B**

### **SITE RECONNAISSANCE PHOTOGRAPHY**

**Coronation Park  
November 21, 2013**



Photo 1: Looking upstream at channel and pedestrian bridge from Lake Ontario.



Photo 2: Looking upstream at channel.  
Note standing water.



Photo 3: Looking upstream at channel and pedestrian bridge.  
Note standing water.



Photo 4: Looking upstream at culvert crossing of parking lot.  
Note standing water.



**Coronation Park  
November 21, 2013**



Photo 5: Looking downstream to Lake Ontario from pedestrian bridge.  
Note standing water.



Photo 6: Looking downstream at pedestrian bridge.



Photo 7: Looking upstream at channel.  
Note standing water.



Photo 8: Looking downstream at channel from pedestrian culvert crossing. Note bank erosion and standing water.



**Coronation Park  
November 21, 2013**



Photo 9: Looking downstream at culvert crossing. Note debris accumulation/blockage and standing water.



Photo 10: Looking upstream at culvert crossing.



Photo 11: Looking upstream along east ditch of Westminster Drive.



Photo 12: Looking upstream along west ditch of Westminster Drive. Note localized pooling and blocked culvert.



**Coronation Park  
November 21, 2013**



Photo 13: Looking upstream along east ditch of Westminster Drive.  
Note ditch plantings and culvert obstruction.



Photo 14: Looking upstream along east ditch of Westminster Drive.



Photo 15: Looking upstream along west ditch of Westminster Drive.  
Note rutting erosion and skew culvert.



Photo 16: Looking upstream along west ditch of Westminster Drive.  
Note standing water in ditch.



**Coronation Park  
November 21, 2013**



Photo 17: Looking upstream along east ditch of Westminster Drive.



Photo 18: Looking downstream at recently constructed armour stone channel from Belvedere Drive.



Photo 19: Looking upstream at open channel adjacent to Lakeshore Road. Note standing water.



Photo 20: Looking at upstream face of culvert crossing of Old Lakeshore Road.



**Coronation Park  
November 21, 2013**



Photo 21: Looking at downstream face of culvert crossing of Old Lakeshore Road. Note flow obstruction (wooden fence).



Photo 22: Looking upstream along south side of Lakeshore Road.



Photo 23: Looking upstream at south-east corner of Lakeshore Road and Third Line.



Photo 24: Looking west along Lakeshore Road across Third Line to open channel.

**Coronation Park  
November 21, 2013**



Photo 25: Looking at downstream face of culvert crossing of Lakeshore Road.



**Coronation Park  
April 16, 2014**



Photo 26: Looking east on south side of Hixon at Tracina.  
Note filled ditch/culvert.



Photo 27: Looking west on north side of Hixon at Tracina.  
Note filled ditch/culvert.



Photo 28: Looking south on Tracina at Hixon.  
Note filled ditch/culvert.



Photo 29: Looking north on Tracina at Hixon.  
Note standing water in ditch.



**Coronation Park  
April 16, 2014**



Photo 30: Beehive CB at north-west corner of Tracina/Hixon.  
Note debris blockage.



Photo 31: Looking downstream at storm sewer outfall at Willowdown Road. Note debris and minor erosion.



Photo 32: Looking at culvert outfall at Willowdown Road.



Photo 33: Looking south-east along west side of Willowdown Road. Note debris blockage of catchbasin & standing water further upstream.



**Coronation Park  
April 16, 2014**



Photo 34: Looking downstream from Woodhaven Park Drive. Note minor bank erosion.



Photo 35: Looking upstream along Woodhaven Park Drive. Note channel erosion.



Photo 36: Downstream face of culvert at Woodhaven Park Drive. Note partial obstruction.



Photo 37: Looking upstream from Woodhaven Park Drive. Note minor bank erosion.



**Coronation Park  
April 16, 2014**



Photo 38: Upstream face of culvert at Woodhaven Park Drive.  
Note partial obstruction.



Photo 39: Looking south along Woodhaven Park Drive.



Photo 40: Downstream face of Sedgewick Crescent culvert.  
Note obstruction and crushing.



Photo 41: Looking west along Sedgewick Crescent.



**Coronation Park  
April 16, 2014**



Photo 42: Upstream face of Sedgewick Crescent culvert.



Photo 43: Looking east along Sedgewick Crescent.  
Note ditch erosion.



Photo 44: Looking upstream at culvert outfall.  
Note sedimentation and ponding.



Photo 45: Looking downstream at outfall ditch.  
Note reverse slope.



**Coronation Park  
April 16, 2014**



Photo 46: Looking downstream at outfall ditch.  
Note flat grade and standing water.



Photo 47: Looking downstream at ditch outfall to forest area.  
Note sedimentation.



Photo 48: Looking upstream at ditch outfall.  
Note exposed erosion blanket and channel erosion.



Photo 49: Looking downstream at forest area.  
Note flat area and lack of channel definition.



**Coronation Park  
April 16, 2014**



Photo 50: Looking downstream at headwall for culvert, and fence for WWTP site.



Photo 51: Looking west along Hixon Street at catchbasin manhole.



Photo 52: Looking upstream at concrete lined channel/storm outfall behind Hixon Street. Note debris accumulation.



Photo 53: Looking at bank erosion adjacent to end of concrete lined channel behind Hixon Street.



**Coronation Park  
April 16, 2014**



Photo 54: Looking downstream at open channel behind Hixon Street.  
Note bank erosion.



Photo 55: Looking downstream at open channel behind Hixon Street.  
Note bank erosion and tree debris.



Photo 56: Looking downstream at partially crushed culvert at Selgrove Crescent and Woodhaven Park Drive.



Photo 57: Looking south along east ditch of Woodhaven Park Drive.  
Note standing water and channel erosion/rutting.



**Coronation Park  
April 16, 2014**



Photo 58: Looking south along west ditch of Woodhaven Park Drive at Selgrove Crescent. Note wet grass.



Photo 59: Looking west along Selgrove Crescent. Note tire tracks and significant erosion.



Photo 60: Looking south along west ditch of Woodhaven Park Drive. Note obstructed catchbasin and crushed culvert.



Photo 61: Looking north along east ditch of Woodhaven Park Drive. Note erosion around catchbasin.



**Coronation Park  
April 16, 2014**



Photo 62: Looking south along west ditch of Woodhaven Park Drive.  
Note standing water.



Photo 63: Curb cut at Lakeshore and Woodhaven Park Drive.  
Note sedimentation.



Photo 64: Looking north along west ditch of Woodhaven Park Drive.



Photo 65: Looking north along east ditch of Woodhaven Park Drive at Lakeshore. Note standing water and partially crushed driveway culvert.



**Coronation Park  
April 16, 2014**



Photo 66: Looking downstream towards Lakeshore Rd from Woodhaven Park Drive. Note standing water & channel obstruction from vegetation.



Photo 67: Looking west along Lakeshore Road



Photo 68: Looking west from catchbasin manhole along Lakeshore Road.



Photo 69: Looking north from catchbasin manhole onto WWTP site.



**Coronation Park  
April 16, 2014**



Photo 70: Undersized PVC culvert outlet on WWTP site.  
Note partial obstruction.



Photo 71: Storm sewer outfall behind Woodhaven Park Drive.  
Note partial obstruction.



Photo 72: Looking downstream along channel behind  
Woodhaven Park Drive. Note minor bank erosion.



Photo 73: Looking downstream at channel from parking lot of  
Jehovah's Witness Hall. Note steep bank.



**Coronation Park  
April 16, 2014**



Photo 74: Upstream face of Lakeshore Road culvert.



Photo 75: Looking upstream from Lakeshore Road culvert.  
Note bank erosion.



Photo 76: Looking upstream at municipal storm sewer outfall and unknown smaller outfall from WWTP site.



Photo 77: Storm sewer outfall adjacent to Lakeshore Road.



**Coronation Park  
April 16, 2014**



Photo 78: Looking upstream at open channel from Lakeshore Road.



Photo 79: Looking downstream at open channel from storm sewer outfall at Lakeshore Road. Note bank erosion.



Photo 80: Looking east along north ditch of Lakeshore Road. Note standing water and erosion/rutting.



Photo 81: Looking along west ditch on Sandwell Drive.



**Coronation Park  
April 16, 2014**



Photo 82: Looking along east ditch on Sandwell Drive.



Photo 83: Looking east along north ditch of Lakeshore Road.  
Note standing water and erosion/rutting.



Photo 84: Looking west along north ditch of Lakeshore Road.  
Note standing water and erosion/rutting.



Photo 85: Looking west along south side of Lakeshore Road.  
Note lack of ditch.



**Coronation Park  
April 16, 2014**



Photo 86: Looking west along south side of Lakeshore Road.  
Note lack of ditch and damage to roadway.



Photo 87: Looking west along south side of Lakeshore Road.  
Note lack of ditch and erosion on side of road.



Photo 88: Looking west along south side of Lakeshore Road.  
Note beginning section of ditch and obstructed culverts.